

Under Review Notification

Raised By: Steven Drouin
Date: 19.01.02

Product #: D117-837
Product Name: Heli-Utility-Basket

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	PP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
D117-837-011	IIN-D117-837 Rev. C	N	N	N	N	N	Y	Y	19-555	CHG#006
D5203-041	D5203-041 Rev. C	N	N	N	N	N	Y	Y	19-555	Revise Drawing

Description of Issue:

Problems with the Strut assembly of the basket,
 See Enginnering for more information

Distribution:

VP Operations Director of Operations Director Quality Assurance QC Coordinator	Director of Engineering Chief Engineer Engineering Project Managers Engineering Clerk	Customer Support Manager Production Engineers Production Planners Purchasing Manager	Technical Support Product Manager - Solutions Provider Supply Chain Director / Senior Buyer Marketing Eugene
---	--	---	---